




MODBAR TECHNICAL BULLETIN

#14

Tap Handle Bushing – Espresso and Steam Handle

Dear Modbar family member,

All espresso and steam actuator handles will now have a brass bushing set opposed to the previous roller bearing design. It will still be important to lubricate the brass bushing and inspect the shoulder bolt during regular scheduled preventive maintenance.



This change started with serial # 2215.

It is now possible to order actuator handles with the updated bushing.

We do not suggest retrofitting the bushing update in old handles.

Please send any questions or orders to:
service@modbar.com

28/02/2018



For technical documents, service and installation guides, please visit
<http://www.modbar.com/support>

Copyright © 2018 Modbar LLC, All rights reserved.
You're receiving this email as a MODBAR authorized
service partner

Our mailing address is:
La Marzocco
Via La Torre 14/H
Scarperia, FI 50038
Italy

MailChimp